









- A PERFORMANCE SPACE (AT GRADE WITH GROUND; SURFACE TBD)
- **B** PAVED SEATING AREAS
- **C** REFURBISHED FOUNTAIN
- **D** BRICK & CMU SEAT WALL WITH PLANTER (TYPE A; 4 TOTAL)
- **E** BRICK & CMU SEAT WALL WITHOUT PLANTER (TYPE B; 7 TOTAL)
- **F** TREE PLANTING AREA WITH GROUNDCOVER AND SILVA CELLS (2 TOTAL)
- **G** 6 FOOT PAVED ADA WALKWAY
- **H** EXISTING LAMPPOST IN NEW LOCATION (4 TOTAL)
- — EXISTING LAMPPOST IN CURRENT LOCATION (6 TOTAL)
- **J** DRINKING FOUNTAIN ON PAVED FOOTPRINT (2 TOTAL)
- **K** PAVED BIKE RACK FOOTPRINT WITH BIKE REPAIR STATION (1 TOTAL)
- NEW/ EXPANDED 7 FOOT SIDEWALK
- M APPROXIMATE CURB-CUT LOCATIONS (6 TOTAL)
- N CONCRETE FOOT FOR XMAS TREE, MAYPOLE, ETC
- — NEW SHADE TREES
- **P** EXISTING TREES
- **Q** MEDIUM-HEIGHT SHRUB WALL
- R LOW-HEIGHT SHRUB WALL
- **S** SHADED GRASS SEATING AREAS WITH MULTIPLE SEATING OPTIONS
- T OLD BUS KIOSK WITH NEW BUMP-OUT

*NOT SHOWN: 2 WATER SPIGOTS; 6-8 ELECTRIC OUTLETS



